

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

858
NW
> 1
1.165 mi.
6149 ft.

VAULT #3562
CROPSEY AVE & BAY 38TH ST
BROOKLYN, NY

NY Spills S103575740
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: VAULT #3562
Address: CROPSEY AVE & BAY 38TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9811904 / 2003-02-20
Facility ID: 9811904
Facility Type: ER
DER Facility ID: 249701
Site ID: 309297
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1998-12-22
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-12-22
CID: 257
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-12-22
Spill Record Last Update: 2003-02-24
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: BILL MURPHY
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis 122093 12-22-98 09:25HRS F. ABBASSI REPORTS, FOUND UNDIAPERABLE SHEEN OF UNKNOWN OIL ON 150 GAL OF WATER IN VS 3562. HOLE IS CONTAINED & NO SEWERS OR WATERWAYS WERE AFFECTED. NO SUMP IN HOLE. SPILL WAS DISCOVERED WHILE CUTTING FOR REMOVAL. 1 LIQUID SAMPLE WAS TAKEN ON A 4-6HR TURNAROUND.ENV. STOP TAG # 12490 WAS PLACED. WILL CALL BACK WITH UPDATE ABOUT PRESSURE TESTING UNIT. UNIT RECORD SHOW PCB TO BE 49 PPM AND WAS INSTALLED BEFORE 1979 ALSO LAYOUT PRINT SHOWS NO SUMP OR SEWERS OR DRAIN IN HOLE CIG NOTIFIED 1006 HRS S.PACE 49874 ***** UPDATE 12-22-98 1030 HRS F.AAASSI UG OS REPORTS HE PRESSURE UNIT AND IT DID NO LEAK. UNIT WILL STILL BE REMOVED WHEN SAMPLE RESULTS RETURN. LAZ #04425 UPDATE: 12/22/98-17:05HRS-LAB SEQ#98-14229-RESULTS <1.00 PPM UPDATE:29-DEC-1998 UNIT WAS REMOVED THE CLEAN UP IS COMPLETE WITH SLIX .TAG#12490 REMOVED. INCIDENT IS CLOSED."

Remarks: "sheen on 150gals of water in underground vault ref #122093 samples taken cleanup waiting results"

All Materials:
Site ID:

309297

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 1072622
Operable Unit: 01
Material ID: 556076
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported